

ZA070A Zero Air

Artikelnummer: UK: 30-1610 (230v) |
EU: 30-1620 (230v) | US: 30-1630 (110v)




Beschreibung

Der Generator ZA070A erzeugt in GC-Anwendungen keine Luft für Detektorgas und entfernt alle Kohlenwasserstoffe aus einer Druckluftquelle, bevor sie in Ihre Instrumente gelangen, um die saubersten Ergebnisse Ihres Detektors zu gewährleisten.



Generator Details

- **Gasarten:** Null-Luft
- **Integrierter Kompressor:** Nein



Hauptmerkmale

- Erzeugt einen konstanten Luftstrom von null Grad mit einem Kohlenwasserstoffgehalt von weniger als 0,1 ppm
- Führt bei Bedarf rund um die Uhr durch
- Ein Generator kann mehrere Instrumente versorgen
- Wenige bewegliche Teile bedeuten wenig Wartung und gewährleisten eine lange Lebensdauer des Generators
- Minimale Einrichtung erforderlich
- 12 Monate umfassende Vor-Ort-Garantie

Technische Spezifikationen

Der Generator ZA070A

Gasart	Null-Luft
Maximaler Gasfluss:	7L/min
Kohlenwasserstoffgehalt:	0.1ppm
Maximale Reinheit:	0.1ppm THC
Startzeit:	40 Minutes
Stromspannung:	230 ± 10% VAC
Frequenz:	50 HZ
Strom:	4.9 Amps
Maximale Betriebstemperatur:	30°C / 86°F
Partikel:	0.01µm
Größe (HxBxT) mm	880 x 430 x 410 mm
Größe (HxBxT) Zoll	34,6 x 16,9 x 16,1 inches
Gewicht des Generators	64kg / 140,8lbs

[PEAK Protected]TM

Peak Scientific gas generators define the benchmark in reliability, convenience and performance in laboratories around the world, and come backed with a 12 month warranty. Beyond this period however you can ensure that your investment continues to be **[Protected]** by our comprehensive generator care cover.

Our world-class aftercare support packages deliver a program of scheduled preventative maintenance whilst giving you the reassurance of instant access to worldwide technical support and priority on-site response in the untimely event of a breakdown.

- For ordering parts visit: www.peakscientific.com/ordering/
- For service plans visit: www.peakscientific.com/service/service-plans/

Peak Scientific UK
Tel: +44 (0)141 812 8100
Fax: +44 (0)141 812 8200

Peak Scientific North America
Tel: +1-800-767-6532
Fax: +1-978-608-9503

Peak Scientific China
Tel: +86 21 5079 1190
Fax: +86 21 5079 1191
For a full list of our worldwide office locations, please visit:
Web: www.peakscientific.com
Email: discover@peakscientific.com

Peak Scientific's Quality Management System conforms to: ISO:9001

